

General Environmental Incident Summary

Incident: 136 **Date/Time Notice:** 11/19/1991 1030 **DEM Incident No:**

Responsible Party: Orian Enterprises

Date Incident: 11/19/1991 **Time Incident:** 0900 **Duration:**

County: Burleigh **Twp:** 139 **Rng:** 76 **Sec:** 28 **Qtr:** NW NW

Lat: 46.82961 **Long:** -100.27820 **Method:** Derived from TRS

Location Description: 1/2 MILE EAST OF MILE MARKER 180 INTERSTATE 94 BY STERLING

Submitted By:

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Joe Boesflug

Sioux Falls, SD

Distance Nearest Occupied Building:

Type of Incident: HYDROCARBON

Description of Released Contaminant: Diesel Fuel

Volume Spilled: 150.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: No

Cause of Incident:

ACCIDENT ALONG I94 RUPTURED TRUCK FUEL TANK. SOIL WAS IN THE DITCH. NORTH DAKOTA HWY DEPT CLEANED THE AREA.

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

